


# Precision Control Indicator

## SI 4200 | Quantity Control Indicator




### Feature

- Quantity control / Counting Indicator (Weight → Quantity)
- External Input : 4 pcs Input Built-in
- Control Relay Output : 6 pcs Output Built-in
- RS232C & Current Loop Standard Built-in
- Precise Quantity Conversion Through "Unit Calibration" Mode
- All Control Relay Will be Output Basis on Quantity Setting
- Visible Output Relay Signal on Panel (02 Green LED)
- Unit Weight Calibration



Auto Packer




Auto Counting Scale

## SI 4300 | Weight Check Control Indicator



### Feature

- Check Weigher / Testing Purpose Indicator
- External Input : 4 pcs Input Built-in
- Control Relay Output : 5 pcs Output Built-in
- RS232C & Current Loop Standard Built-in
- Weight Check Mode : Photo Sensor Mode / Peak Hold Mode
- Hold Tracking Mode : Hold Set (Over Empty)  
Hold Reset (Under Empty)
- Under / Pass / Over / N.G Count Mode (Selectable)



Auto Check Weigher




Tester

## SI 4400 | Packaging Control Indicator



### Feature

- Professional Packer / Filler Control Indicator
- External Input : 4 pcs Input Built-in
- Control Relay Output : 6 pcs Output Built-in
- RS232C & Current Loop Standard Built-in
- Automatic Free Fall Compensation Function
- Compensate Even "Minus(-) Free Fall" Value



Auto Packer

Weighing & Discharging

Filler